						Q.	Code:	533957					
	Reg. No.								10.	List t	he applications of WJM process.		
	<b>RF / RTFCH DFCRFF FX</b> /	MIN		JS N	<u>і    і                               </u>	2023					PART- B (5 x 14		
	Fourth Sen	nester	AIIO	10, 1	1A1	2023							
	ME18402 – MACHINE TOOLS AN	D MA	CHIN	ING	G PRO	DCESSES			11. (a)	(i)	In an orthogonal cutting operation, following		
	(Mechanical En	gineeri	ng)						()	(-)	Cutting speed = $25m/min$ , Width of cut =2.		
	(Regulation 201	8 / 201	<b>8A)</b>								Chip thickness =0.4 mm, cutting force = 1400		
	: 3 HOURS	ONT			Μ	AX. MARK	KS: 100	) DDT			rake angle = $5^0$		
	RSE STATEN DMES	IENT						LEVEL			Calculate:		
CO 1	1 The students will be able to estimate the cutting force during machining, identify the type of 3 chips for a given material and will justify the tool angles for a given single point cutting tool										1. Shear angle 2. Friction angle 3. Chip flow		
										<i>(</i> <b>••</b> )	Power consumed at tool in kW		
CO 2	The students will be able to elucidate the const	ruction	details	and w	vill pre	pare the ope	eration	3		(ii)	What is the difference between a tool signatu		
	planning sheet for a given part diagram												
CO 3	3 Students will choose appropriate gear manufacturing process and its associate machine tools 3							3	(D)	(1)	The following cutting speed of cutting time		
	for gear manufacturing	1.				. ,		2			Cutting grand V 28 m/min		
CO 4	Students can classify and choose among the fini	shing p	rocesses	as pe	er requ	irement	1	3			Cutting speed, V 28 m/mm		
105	students will be able to choose appropriate not	1 - trac	intional	machi	ining j	processes ba	sed on	3			Calculate		
	then principle and minitation $\mathbf{PADT} = \mathbf{A} (10 + 2)$	- 20 M	larks)								a) n and C		
	Answer all O	- 20 IV	1 <b>a1 KS</b> )								b) Suggest the cutting speed for a tool lit		
		uestion	13)				CO	RBT			c) Calculate the tool life for a cutting spe		
								LEVEL			d) Calculate the percentage increase in to		
•	You have got a job order for machining cast iron a	and alu	minium	. As a	a mac	hinist which	1 1	3			of 20 m/min in comparison with the tool		
	one will be easier to machine and what are the challe	enges to	be ove	rcom	e whil	e machining	5			(ii)	How the wear rate varies with respect to the		
	these materials?							_			cutting speed? Explain graphically.		
•	Why machining at higher cutting speeds yields less	er tool l	ife? Sug	ggest	some	cutting tools	5 1	3					
	that can be selected for machining at higher cutting	speeds		1 1 1 7 7 1		· ~	<b>•</b>		12. (a)	(i)	A lathe has four steps of cone pulley, the dia		
•	A cylindrical job of $\phi$ 250 X 1250 mm length has	to be m	achinec	i. Wh	at spe	cification o	t 2	3			130mm, 170 mm and 210 mm respectively		
	the lathe must be referred and justify.	1 / 1	1		71 • 1	1 · 1	•	•			which is connect to the motor runs at 100 rpi		
•	A larger diameter workpiece has to be machined in	batch p	producti	on. W	Vhich	machine ha	<b>5</b> 2	3			have 16, 48, 16 and 48 teeth respectively. Dra		
	to be selected and justify?	• 11	1.0	C	.1	1	•	•			the various speeds of the spindle. If the cu		
•	A lathe headstock has spur gears for changing the sp	indle s	peed. U	ne or	the sp	ur gear teeti	1 3	3			anindle speed to be selected for each oper		
	has broken. What gear parameters must be referr		nanulac	ture t	the ge	ar and wha	l				workniece is 40 mm		
-	Machine tool you will select to manufacture the bro	ken gea	ar? Justi	IY. What		in a ta al aar		2		(ii)	Identify the operation performed in Figure 3-		
•	A round rod has to be converted into polygon have	ng o su	irfaces.	wnau	l maci	line tool car	1 3	3		(11)			
,	While referring to the product diagram how w	ill vou	way: decide	wha	athar	finishing o	r 1	3					
•	superfinishing is required or not? Justify with an ex	iii you ample	ucciuc		culoi	iiiisiiiig 0		5					
2	What programming mode has to be selected for mac	hining	the nart	s show	wn in	Figure 1 and	1 1	3					
•	2 respectively? Justify and what is the respective G	codes	ine pure	5 5110	** 11 111	i iguie i uit	• •	0			Workpiece		
	2 respectively. Fushing and what is the respective G	coucs.									Tool Feed		
	<u>&lt; 50</u>		10.0	ia . 6 holes	5								
	D,6 D,6 D,6 D,6		- 4	•	•						Figure 3		
					A .								
	$\overline{1}$	kô .			Ψ								



9. Identify the mechanism of material removal, transfer media and energy source for EDM. 5

Figure 5

2

## $RT-B(5 \times 14 = 70 \text{ Marks})$

		Marks	CO	RBT LEVEL
n, following ob n of cut =2.5 m force = 1400 N,	servations were made im, feed – 0.24 mm/rev, feed force = 400 N, Tool clocity 4. Shear strain 5	(10)	1	3
			4	•
tool signature a	and a tool nomenclature?	(4)	I	2
atting time obse	rvations have been	(10)	1	3
28 m/min	41 m/min			
75 min	18 min			
for a tool life o a cutting speed ncrease in tool with the tool life respect to the y.	f 50 minutes of 50 m/min life for a cutting speed e at 50 m/min. cutting time for various	(4)	1	2
lley, the diame respectively. T as at 100 rpm. ectively. Draw t e. If the cuttin and 10m/min res each operation	ter of each being 90mm, The counter shaft pulley The gears A, B, C and D the arrangement and find g speed for turning and pectively what should be n if the diameter of the	(10)	2	3
in Figure 3-6.		(4)	2	2



Figure 4



Figure 6

## **O. Code:533957**

(10)

(4)

(10)

(4)

2

3

3

2

3

2

3

3

3

3

3

3

3

**(b)** 

## (**OR**)

- For repetitive manufacturing of the component shown in the figure 7 **(b)** (i)
  - 1. Suggest a suitable machine tool
  - 2. List out the sequence of machining operations
  - 3. Cutting tools required and

(ii)

4. Position the cutting tools at appropriate place on the machine tool and show it with a neat sketch.



Figure 7 (All dimensions are in millimeter) What is the purpose of a feed rod and lead screw in a lathe?

- 13. (a) (i) What mechanism are employed in a shaper for converting a rotary into a reciprocating motion? Explain how a quick return tool motion is achieved in a shaper.
  - A component shown in the figure 8 has to be manufactured and the job (ii) order quantity is small. Select a suitable machine, list the sequence of operations and also the associated cutter. (Drill size standards are 6, 8.50, 12 mm)



Figure 8 (All Dimensions are in millimeter)

- (**OR**)
- A helical gear of 93 teeth has to be manufactured by gear milling. **(b)** (i) (10) 3 Determine what indexing method can be used and calculate the hole spaces to be moved.
  - (Use the index plate which has 21, 23, 27, 29, 31 and 33 hole circles)
  - Shanti Gears in Coimbatore is manufacturing gears through the year. (4) (ii) What kind of machine tools will be used for manufacturing gears? Justify your statement.
- 14. (a) (i) An engine cylinder has been manufactured by casting process. The bore (10) 4 has to be machined to the closer dimensional tolerance of 0.002 mm. What will be sequence of operations and explain the respective machine tools
  - A grinding wheel is specified as A 24 K 7 V. What does each letter (ii) (4) indicates?
    - (OR)





Figure 9 (All dimensions are in millimeter)

- (i) Write short notes on electrical discharge m 15. (a) applications and advantages.
  - (ii) How the non-conventional machining proces the energy sources? List them
    - (**OR**)
  - (i) Explain the working principle of a Ultrasoni diagram and also list down the process parame removal rate.
  - List down the applications of abrasive jet ma (ii)

## PART- C (1 x 10

(Q.No.16 is co

16. A component shown in the figure 10 has to b quantity. What machine tool you will select, operations, the corresponding tools and also the machining time.



4

nachining and list down its	(10)	5	2
sses are classified based on	(4)	5	2
ic machining with a simple eters that affects the material	(10)	5	2
chining.	(4)	5	2
<u>) = 10 Marks)</u> ompulsory)			
	Marks	CO	RBT LEVEL
be manufactured in a small list down the sequence of	(10)	2	3